

<b>8.4 Bumpers:</b>		
Inspect:		
a) bumper and rebar	<ul style="list-style-type: none"> <li>a) - front bumper missing on a vehicle, other than a modified vehicle manufactured before January 1, 1970 that is not a raised vehicle</li> <li>- rear bumper missing on a vehicle, other than a modified vehicle manufactured before January 1, 1970 or a truck</li> <li>- broken, insecure, torn portion or ends protruding so as to create a hazard, perforated, splintering material, or modifications that lessen performance designed by OEM</li> </ul>	

ITEM AND METHOD OF INSPECTION	REJECT IF	
	GENERAL CONDITIONS	HAZARDOUS CONDITIONS
	<ul style="list-style-type: none"> <li>- trucks: lowest part of front bumper higher than 740 mm (29 in.) from ground</li> <li>- vertical surface less than 50 mm (2 in.)</li> <li>- does not extend to outside edges of frame rails, or does not extend from the frame rail to the outer edge of the tire if the fender does not extend to 90° to the front of the vertical centre line of the wheel</li> <li>- extends past the body line and the ends do not angle towards the body</li> <li>- not attached in original mounting position</li> </ul>	